

GENERAL RADIO COMPANY




Figure 4. VSWR seen looking back into output connector of a typical Type 874-GAL Adjustable Attenuator.



Figure 3. Frequency Correction Factor.